



The two small circles are the starting points for the drill bit used for starting the slots. All other lines are the :mill to lines". I plan to use a 5/16 mill for the width and then use the largest mill I have that will fit into the layout lines for the radius. Probably not the method a machinist would use!

Alternative is to use the CNC machine for the slots. I may do that for the aluminum jaws.

Main purpose of this drawing is for manual layout of slot dimensions. I use this for visual confirmation while milling just in case my digital readouts hiccup.. Sometimes they do!

4" KurtStyleVise	
ViseJawSym_DetailsDrilling	
01/06/2025	JR