



Note: 0.149 holes are tapped 10-24 at 2 places.
 Two holes are at the tapered end but only 1 is needed with others being optional.
 The Clamp screw is threaded 1/4-20.

Multiple arms could be made for special purpose.